INSURANCE SERVICES OFFICE, INC. HYDRANT FLOW DATA SUMMARY

| Community Tubac Fd | | | | |
|-----------------------------|------------|--|--------------|--------------|
| | ARIZONA | Witnessed by: Insurance Services Office | | |
| County Arizona(Santa Cruz), | State (02) | witnessed by. Histilance Services Office | Survey Date: | Jun 12, 2014 |

| | | | | FLOW - GPM | | | | PRESSURE FLOW -AT 20 PSI | | | | | | |
|------|--------|-------------------------------------|---------------------------------|----------------------------|--|---|-------|--------------------------|--------|-----------|--------|----------------|------------|----------------|
| | | | | $Q=(29.83(C(d^2)p^{0.5}))$ | | | P | PSI | | | | | | |
| TEST | TYPE | TEST LOCATION | SERVICE | II | NDIVIDUAL | | TOTAL | STATIC | RESID. | NEEDED | AVAIL. | REMARKS*** | MODEL TYPE | FLOW TEST DATE |
| NO. | DIST.* | | | HYDRANTS | | | | | ** | | | | | |
| | | | EPCOR Tubac Water | | | | | | | | | | | |
| 1 | | Otero Rd | System, 1 | 980 | 0 | 0 | 980 | 81 | 48 | 1750 | 1400 | (B)-(913 gpm) | FTPC | 10/04/2019 |
| | | | EPCOR Tubac Water | | | | | | | | | | | |
| 2 | | East Frontage Rd and Plaza Rd | System, 1 | 750 | 0 | 0 | 750 | 55 | 25 | 2250 | 800 | (B)-(913 gpm) | FTPC | 10/04/2019 |
| | | | EPCOR Tubac Water | | | | | | | | | | | |
| 3 | | Tubac Rd and Hasselbarth Ln | System, 1 | 560 | 0 | 0 | 560 | 59 | 21 | 2000 | 550 | (B)-(913 gpm) | FTPC | 10/04/2019 |
| | | | EPCOR Tubac Water | | | | | | | | | | | |
| 4 | | Primeria Alta and Palo Parado | System, 2 | 1060 | 0 | 0 | 1060 | 75 | 69 | 500 | 3500 | (B)-(310 gpm) | FTPC | 10/04/2019 |
| | | | EPCOR Tubac Water | | | | | | | | | | | |
| 5 | | Cerro Pelon Ct and Western Saddle | System, 3 | 530 | 0 | 0 | 530 | 96 | 21 | 500 | 550 | (B)-(256 gpm) | FTPC | 10/04/2019 |
| | | | Liberty Utilities Rio Rico | | | | | | | | | | | |
| 6 | | Camino Josefina and Venida Patricia | 2 / | 1240 | 0 | 0 | 1240 | 60 | 55 | 1250 | 3800 | | FTPC | 10/04/2019 |
| _ | | | Liberty Utilities Rio Rico | | _ | _ | | | | | | | | |
| 7 | | Pendlton Rd and Pastor | System, Zone 2 | 750 | 0 | 0 | 750 | 145 | 45 | 500 | 850 | | FTPC | 10/04/2019 |
| | | | Liberty Utilities Rio Rico | | | | | | | • • • • • | | | TIMP G | 40/04/2040 |
| 8 | | Plaza Rd and Hasselbarth | System, Zone 1 | 750 | 0 | 0 | 750 | 50 | 22 | 2000 | 800 | | FTPC | 10/04/2019 |
| 0 | | | Liberty Utilities Rio Rico | 1020 | 0 | 0 | 1020 | | 40 | 2000 | 1.600 | | ETDC | 10/04/2010 |
| 9 | | Avenida Goya and Calle Frida Kahlo | <i>y</i> , | 1020 | 0 | 0 | 1020 | 55 | 40 | 2000 | 1600 | | FTPC | 10/04/2019 |
| 10 | | D - 1-14 - D 1 1 X - 11 X Z | Liberty Utilities Rio Rico | 750 | 0 | 0 | 750 | 120 | 20 | 500 | 750 | | ETDC | 10/04/2010 |
| 10 | | Pendelton Rd and Valley View | System, Zone 1 Baca Float Water | 750 | 0 | 0 | 750 | 120 | 20 | 500 | /50 | | FTPC | 10/04/2019 |
| 12 | | Entrance of Calle Bario De Tubac | Company, Main | 790 | 0 | 0 | 790 | 36 | 24 | 1500 | 900 | (D) (709 oper) | FTPC | 10/04/2019 |
| 12 | | Entrance of Cane Barlo De Tubac | Company, Main | /90 | U | U | /90 | 30 | 24 | 1300 | 900 | (B)-(708 gpm) | FIFC | 10/04/2019 |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | [| | | | | | | | | |

THE ABOVE LISTED NEEDED FIRE FLOWS ARE FOR PROPERTY INSURANCE PREMIUM CALCULATIONS ONLY AND ARE NOT INTENDED TO PREDICT THE MAXIMUM AMOUNT OF WATER REQUIRED FOR A LARGE SCALE FIRE CONDITION

THE AVAILABLE FLOWS ONLY INDICATE THE CONDITIONS THAT EXISTED AT THE TIME AND AT THE LOCATION WHERE TESTS WERE WITNESSED.

^{*}Comm = Commercial; Res = Residential.

^{**}Needed is the rate of flow for a specific duration for a full credit condition. Needed Fire Flows greater than 3,500 gpm are not considered in determining the classification of the city when using the Fire Suppression Rating Schedule.

^{*** (}A)-Limited by available hydrants to gpm shown. Available facilities limit flow to gpm shown plus consumption for the needed duration of (B)-2 hours, (C)-3 hours or (D)-4 hours.